



BigJoys Amusement Equipment Co.,Ltd







NO.238 Tongbai road,zhengzhou,China 450007


Website: www.big-joys.com

Email: info@big-joys.com

Tel:0086-371-67951289

All Slides' price is based on **FOB Tianjin Port**,China. Including CE/UL Blower

Inflatable Slide					
Item#	Spec.(Feet/Meter)	Material	Unit Price (FOB Tianjin,China)	Picture	Blower
BJ-S01	39'*20'*23' (12mx6mx7mH)	1000D,18Oz 0.55mm PVC	US\$3,135		CE/UL blower,Repair kits included
	33'*20'*22' (10mx6mx6.5mH)		US\$2,586		
	27'*17'*23' (8mx5mx7mH)		US\$1,866		
BJ-S02	40'*20'*26' (12mx6mx8.5mH)	1000D,18Oz 0.55mm PVC	US\$2,760		CE/UL blower,Repair kits included
BJ-S03	50'*23'*30' (15mx7mx9mH)	1000D,18Oz 0.55mm PVC	US\$4,253		CE/UL blower,Repair kits included
BJ-S04	27'*20'*18' (8mx6mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$2,133		CE/UL blower,Repair kits included
BJ-S05	20'*13'*17' (6mx4mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,338		CE/UL blower,Repair kits included
BJ-S06	20'*13'*17' (6mx4mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,338		CE/UL blower,Repair kits included

BJ-S07	18.4'*26'*25' (8.5x5.5x7.5mH)	1000D,18Oz 0.55mm PVC	US\$2,100		CE/UL blower,Repair kits included
BJ-S08	39'*17'*17' (11mx5mx5mH)	1000D,18Oz 0.55mm PVC	US\$2,300		CE/UL blower,Repair kits included
BJ-S09	30'*13'*17' (9mx4mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,760		CE/UL blower,Repair kits included
BJ-S10	13'*25'*18' (7.5mx4mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,480		CE/UL blower,Repair kits included
BJ-S11	100'*43'*36' (30mx14mx11mH)	1000D,18Oz 0.55mm PVC	US\$21,550		CE/UL blower,Repair kits included
BJ-S12	26'*16'*19' (8.5mx5mx5.7mH)	1000D,18Oz 0.55mm PVC	US\$2,160		CE/UL blower,Repair kits included
BJ-S13	162'*49'*45' (50mx15mx13.5mH)	1000D,18Oz 0.55mm PVC	US\$13,340		CE/UL blower,Repair kits included
	100'*43'*33' (30mx13mx10mH)		US\$9,820		
BJ-S14	37'*18'*27' (12mx5.5mx8mH)	1000D,18Oz 0.55mm PVC	US\$4,730		CE/UL blower,Repair kits included
BJ-S15	41'*20'*26' (12mx6mx8.5mH)	1000D,18Oz 0.55mm PVC	US\$4,200		CE/UL blower,Repair kits included

BJ-S16	36'*18'*21' (11mx5.5mx6mH)	1000D,18Oz 0.55mm PVC	US\$2,410		CE/UL blower,Repair kits included
BJ-S17	20'*13'*17' (6mx4mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,410		CE/UL blower,Repair kits included
BJ-S18	20'*12'*18' (6mx3.6mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,278		CE/UL blower,Repair kits included
BJ-S19	49'*28'*31' (15mx8.5mx9.5mH)	1000D,18Oz 0.55mm PVC	US\$4,230		CE/UL blower,Repair kits included
	27'*27'*18' (8mx8mx5.5mH)		US\$3,300		
BJ-S20	39'*20'*35' (12mx6mx10.5mH)	1000D,18Oz 0.55mm PVC	US\$3,510		CE/UL blower,Repair kits included
BJ-S21	28'*14'*21.5' (8.5mx4.2mx6.5mH)	1000D,18Oz 0.55mm PVC	US\$1,650		CE/UL blower,Repair kits included
BJ-S22	30'*13'*16' (9mx4mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,680		CE/UL blower,Repair kits included
BJ-S23	28'*20'*18' (8.5mx6mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$2,160		CE/UL blower,Repair kits included
BJ-S24	25'*18'*18' (7.5mx5.5mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,950		CE/UL blower,Repair kits included

BJ-S25	33'*26'*29' (10mx8.5mx8.8mH)	1000D,18Oz 0.55mm PVC	US\$5,680		CE/UL blower,Repair kits included
BJ-S26	37'*18'*24' (11mx5.5mx7mH)	1000D,18Oz 0.55mm PVC	US\$2,580		CE/UL blower,Repair kits included
BJ-S27	50'*28'*34' (15mx8.5mx10.2mH)	1000D,18Oz 0.55mm PVC	US\$5,988		CE/UL blower,Repair kits included
BJ-S28	20'*13'*18' (6mx4mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,669		CE/UL blower,Repair kits included
BJ-S29	20'*8.2'*11.5' (6mx2.5mx3.5mH)	1000D,18Oz 0.55mm PVC	US\$730		CE/UL blower,Repair kits included
BJ-S30	30'*15'*18' (9mx4.5mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,935		CE/UL blower,Repair kits included
BJ-S31	40'*23'*20'H (12mx7mx6mH)	1000D,18Oz	US\$3,100		CE/UL blower,Repair kits included
BJ-S32	33'*20'*18'H (10mx6mx5.5mH)	1000D,18Oz	US\$2,566		CE/UL blower,Repair kits included
BJ-S33	33'*21.5'*18' (10mx6.5mx5.5mH)	1000D,18Oz	US\$2,630		CE/UL blower,Repair kits included

BJ-S34	30'*17'*20' (9mx5mx6mH)	1000D,18Oz 0.55mm PVC	US\$1,930		CE/UL blower,Repair kits included
BJ-S35	20'*13'*17' (6mx4mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,360		CE/UL blower,Repair kits included
BJ-S36	27'*13'*23' (8mx4mx7mH)	1000D,18Oz 0.55mm PVC	US\$1,763		CE/UL blower,Repair kits included
BJ-S37	33'*17'*20' (10mx5mx6mH)	1000D,18Oz 0.55mm PVC	US\$1,980		CE/UL blower,Repair kits included
BJ-S38	27'*13'*20' (8mx4mx6mH)	1000D,18Oz 0.55mm PVC	US\$1,695		CE/UL blower,Repair kits included
BJ-S39	33'*33'*15' (10mx10mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$3,920		CE/UL blower,Repair kits included
BJ-S40	30'*17'*20' (9mx5mx6mH)	1000D,18Oz 0.55mm PVC	US\$2,130		CE/UL blower,Repair kits included
BJ-S41	48.3'*28'*22' (14.5mx8.5mx6.7mH)	1000D,18Oz 0.55mm PVC	US\$5,220		CE/UL blower,Repair kits included

BJ-S42	40'*23' (12mx7m)	1000D,18Oz 0.55mm PVC	US\$3,310		CE/UL blower,Repair kits included
BJ-S43	45'*23' (14mx7m)	1000D,18Oz 0.55mm PVC	US\$3,620		CE/UL blower,Repair kits included
BJ-S44	40'*23' (12mx7m)	1000D,18Oz 0.55mm PVC	US\$3,180		CE/UL blower,Repair kits included
BJ-S45	40'*17' (12mx5m)	1000D,18Oz 0.55mm PVC	US\$2,820		CE/UL blower,Repair kits included
BJ-S46	50'*23' (15mx7m)	1000D,18Oz 0.55mm PVC	US\$3,386		CE/UL blower,Repair kits included
BJ-S47	15'*8'*8' (4.5mx2.4mx2.4mH)	1000D,18Oz 0.55mm PVC	US\$920		CE/UL blower,Repair kits included
BJ-S48	16'*16'*9' (4.9mx4.9mx2.8m)	1000D,18Oz 0.55mm PVC	US\$1,230		CE/UL blower,Repair kits included
BJ-S49	33'*18'*18.8' (10mx5.5mx5.65m)	1000D,18Oz 0.55mm PVC	US\$2,090		CE/UL blower,Repair kits included

BJ-S50	30'*13'*13' (9mx4mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,536		CE/UL blower,Repair kits included
BJ-S51	27'*17'*20' (8mx5mx6mH)	1000D,18Oz 0.55mm PVC	US\$1,768		CE/UL blower,Repair kits included
BJ-S52	20'*17'*17' (6mx5mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,426		CE/UL blower,Repair kits included
BJ-S53	25'*17'*18' (7.5mx5mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,780		CE/UL blower,Repair kits included
BJ-S54	40'*15'*20' (12mx4.5mx6mH)	1000D,18Oz 0.55mm PVC	US\$2,500		CE/UL blower,Repair kits included
BJ-S55	18'x8'x8'H (5.5mx2.5mx2.5mH)	1000D,18Oz 0.55mm PVC	US\$660		CE/UL blower,Repair kits included

*1.The above price including CE/UL Blowers,Repair kit bag,PVC Tarpaulin is 0.55mm Thick

*2.Workmanship: Double stitching everywhere,and quadruple stitching at critical points

*3.Slides are made complying with European **NEN Norms 14960.Suitable for rental business**

*4.Dimension,Color&Price are changed without notice,Price is subject to our confirmation

*5.Price is based on **FOB Tianjin port,China**

*6.Packing in Carpet(Inner)+PVC Bag(Outer)

*7.Payment to be made by Bank Wire Transfer(T/T),Western Union or Paypal