



BigJoys Amusement Equipment Co.,Ltd

NO.238 Tongbai road,zhengzhou,China 450007

Website: www.big-joys.com










Email: info@big-joys.com


Tel:0086-371-67951289

Inflatable Obstacle

Item#	Spec.(Feet/Meter)	Material	Unit Price (FOB Tianjin,China)	Picture	Blower
BJ-O01	52.5'x13'x12' (16mx4mx3.6mH)	1000D,18Oz 0.55mm PVC	US\$2,490		CE/UL blower,Repair kits included
BJ-O02	42'x12'x14' (12.5mx3.6mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$2,060		CE/UL blower,Repair kits included
BJ-O03	52'x12'x16' (15.5mx3.6mx5mH)	1000D,18Oz 0.55mm PVC	US\$2,300		CE/UL blower,Repair kits included
BJ-O04	53'x13'x14' (16mx4mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$2,400		CE/UL blower,Repair kits included
BJ-O05	27'x11.5'x15' (8mx3.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,450		CE/UL blower,Repair kits included
BJ-O06	40'x39'x18' (12mx11.7mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$5,200		CE/UL blower,Repair kits included
BJ-O07	30'x20'x10' (9mx6mx3mH)	1000D,18Oz 0.55mm PVC	US\$2,160		CE/UL blower,Repair kits included

BJ-O08	17'*13'*10' (5mx4mx3mH)	1000D,18Oz 0.55mm PVC	US\$1,036		CE/UL blower,Repair kits included
BJ-O09	72'*13'*18' (22mx4mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$3,400		CE/UL blower,Repair kits included
BJ-O10	40'*13'*13' (12mx4mx4mH)	1000D,18Oz 0.55mm PVC	US\$2,100		CE/UL blower,Repair kits included
BJ-O11	33'*12'*11' (10mx3.6mx3.3mH)	1000D,18Oz 0.55mm PVC	US\$1,435		CE/UL blower,Repair kits included
BJ-O12	50'*10'*15' (15mx3mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,850		CE/UL blower,Repair kits included
BJ-O13	34'*13'*11' (11mx4mx3.3mH)	1000D,18Oz 0.55mm PVC	US\$1,950		CE/UL blower,Repair kits included
BJ-O14	39'*11'*12' (12mx3.3mx3.6mH)	1000D,18Oz 0.55mm PVC	US\$1,900		CE/UL blower,Repair kits included
BJ-O15	59'*13'*20' (18mx4mx6mH)	1000D,18Oz 0.55mm PVC	US\$2,930		CE/UL blower,Repair kits included
BJ-O16	66'*11'*16' (20mx3.3mx5mH)	1000D,18Oz 0.55mm PVC	US\$2,785		CE/UL blower,Repair kits included

BJ-O17	40'*40'*6' (12mx12mx1.8mH)	1000D,18Oz 0.55mm PVC	US\$3,800		CE/UL blower,Repair kits included
BJ-O18	23'x23'x10'H (7mx7mx3mH)	1000D,18Oz 0.55mm PVC	US\$1,960		CE/UL blower,Repair kits included
BJ-O19	62'x15'x13'H (20mx4.5mx4mH)	1000D,18Oz 0.55mm PVC	US\$3,440		CE/UL blower,Repair kits included
BJ-O20	40'x10'x10'H (12mx3mx3mH)	1000D,18Oz 0.55mm PVC	US\$1,756		CE/UL blower,Repair kits included
BJ-O21	72'x11'x16'H (21.6mx3.5mx4.8mH)	1000D,18Oz 0.55mm PVC	US\$3,020		CE/UL blower,Repair kits included
BJ-O22	72'x11'x16'H (21.6mx3.5mx4.8mH)	1000D,18Oz 0.55mm PVC	US\$3,020		CE/UL blower,Repair kits included
BJ-O23	65'x11'x13'H (19.5mx3.5mx4mH)	1000D,18Oz 0.55mm PVC	US\$2,800		CE/UL blower,Repair kits included
BJ-O24	52'x11'x13'H (15.6mx3.5mx4mH)	1000D,18Oz 0.55mm PVC	US\$2,390		CE/UL blower,Repair kits included
BJ-O25	52'x10'x15'H (15.6mx3mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$2,200		CE/UL blower,Repair kits included

BJ-O26	52'x10'x14'H (15.6mx3mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,985		CE/UL blower,Repair kits included
--------	----------------------------------	--------------------------	-----------	--	---

*The above price including CE/UL Blowers,Repair kit bag,PVC Tarpaulin is 0.55mm Thick

*Workmanship: Double stitching everywhere,and quadruple stitching at critical points

*Obstacles are made complying with European **NEN EN-14960.Suitable for rental business**

*Dimension,Color&Price are changed without notice,Price is subject to our confirmation

*Price is based on FOB Tianjin port,China

*Packing in Carpet(Inner)+PVC Bag(Outer)

*Payment to be made by Bank Wire Transfer(T/T),Western Union or Paypal