



BigJoys Amusement Equipment Co.,Ltd





NO.238 Tongbai road,zhengzhou,China 450007










Website: www.big-joys.com

Email: info@big-joys.com









Tel:0086-371-67951289



Inflatable Combo

Item#	Spec.(Feet/Meter)	Material	Unit Price (FOB Tianjin,China)	Picture	Blower
BJ-COB01	22'*18'*13' (6.5mx5.5mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,460		CE/UL blower,Repair kits included
BJ-COB02	23'*11.5'*13' (7mx3.5mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,630		CE/UL blower,Repair kits included
BJ-COB03	18'*13'*13' (5.5mx4mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,050		CE/UL blower,Repair kits included
BJ-COB04	35'*13'*15' (10.5mx4mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,700		CE/UL blower,Repair kits included
BJ-COB05	26'*15'*12' (8mx4.5mx3.5mH)	1000D,18Oz 0.55mm PVC	US\$1,533		CE/UL blower,Repair kits included
BJ-COB06	20'*19'*12' (6mx5.7mx3.5mH)	1000D,18Oz 0.55mm PVC	US\$1,400		CE/UL blower,Repair kits included
BJ-COB07	30'*13'*14' (9mx4mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,620		CE/UL blower,Repair kits included

BJ-COB08	23'*13'*14' (7mx4mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,266		CE/UL blower,Repair kits included
BJ-COB09	30'*13'*14' (9mx4mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,600		CE/UL blower,Repair kits included
BJ-COB10	30'*13'*15' (9mx4mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,620		CE/UL blower,Repair kits included
BJ-COB11	30'*13'*14' (9mx4mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,760		CE/UL blower,Repair kits included
BJ-COB12	24'*24'*14' (7.2mx7.2mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$2,345		CE/UL blower,Repair kits included
BJ-COB13	25'*17'*17' (8.5mx5mx5mH)	1000D,18Oz 0.55mm PVC	US\$1,780		CE/UL blower,Repair kits included
BJ-COB14	22'*20'*14' (6.6mx6mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$1,520		CE/UL blower,Repair kits included
BJ-COB15	33'*16'*18' (10mx5mx5.5mH)	1000D,18Oz 0.55mm PVC	US\$1,900		CE/UL blower,Repair kits included
BJ-COB16	20'*16'*10' (6mx5mx3mH)	1000D,18Oz 0.55mm PVC	US\$1,350		CE/UL blower,Repair kits included

BJ-COB17	19'*16'*10' (6mx5mx3mH)	1000D,18Oz 0.55mm PVC	US\$1,420		CE/UL blower,Repair kits included
BJ-COB18	24'*20'*14' (7.2mx6mx4.2mH)	1000D,18Oz 0.55mm PVC	US\$2,300		CE/UL blower,Repair kits included
BJ-COB19	28'*13'*13' (8.5mx4mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,700		CE/UL blower,Repair kits included
BJ-COB20	16'*16'*13' (5mx5mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,150		CE/UL blower,Repair kits included
BJ-COB21	20'*20'*13' (6mx6mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,986		CE/UL blower,Repair kits included
BJ-COB22	20'*15'*15' (6mx4.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,195		CE/UL blower,Repair kits included
BJ-COB23	16'*16'*13' (5mx5mx4mH)	1000D,18Oz 0.55mm PVC	US\$1,150		CE/UL blower,Repair kits included
BJ-COB24	31'x10'x12'H (9.3mx3mx3.6mH)	1000D,18Oz 0.55mm PVC	US\$1,420		CE/UL blower,Repair kits included
BJ-COB25	29'x11'x15'H (8.8mx3.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,460		CE/UL blower,Repair kits included

BJ-COB26	29'x11'x15'H (8.8mx3.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,550		CE/UL blower,Repair kits included
BJ-COB27	29'x11'x15'H (8.8mx3.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,460		CE/UL blower,Repair kits included
BJ-COB28	18'x15'x15'H (5.5mx4.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,220		CE/UL blower,Repair kits included
BJ-COB29	18'x15'x15'H (5.5mx4.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,220		CE/UL blower,Repair kits included
BJ-COB30	32'x16'x17'H (9.6mx5mx5.1mH)	1000D,18Oz 0.55mm PVC	US\$1,930		CE/UL blower,Repair kits included
BJ-COB31	32'x16'x17'H (9.6mx5mx5.1mH)	1000D,18Oz 0.55mm PVC	US\$1,930		CE/UL blower,Repair kits included
BJ-COB32	18'x15'x15'H (5.5mx4.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,240		CE/UL blower,Repair kits included
BJ-COB33	18'x15'x15'H (5.5mx4.5mx4.5mH)	1000D,18Oz 0.55mm PVC	US\$1,240		CE/UL blower,Repair kits included

BJ-COB34	42'x19'x17'H (12.6mx5.7mx5.1mH)	1000D,18Oz 0.55mm PVC	US\$2,950		CE/UL blower,Repair kits included
BJ-COB35	31'x13'x17'H (9.3mx4mx5.1mH)	1000D,18Oz 0.55mm PVC	US\$1,650		CE/UL blower,Repair kits included

*The above price including CE/UL Blowers,Repair kit bag,PVC Tarpaulin is 0.55mm Thick

*Workmanship: Double stitching everywhere,and quadruple stitching at critical points

*Combos are made complying with European **NEN Norms 14960.Suitable for rental business**

*Dimension,Color&Price are changed without notice,Price is subject to our confirmation

*Price is based on FOB Tianjin port,China

*Packing in Carpet(Inner)+PVC Bag(Outer)

*7.Payment to be made by Bank Wire Transfer(T/T),Western Union or Paypal