

BigJoys Amusement Equipmemt Co.,Ltd NO.238 Tongbai road,zhengzhou,China 450007

Website: www.big-joys.com

Email: info@big-joys.com

Tel:0086-371-67951289

Inflatable Water Park Items						
Item#	Spec.(Feet)	Material	Unit Price (US\$ EXW)	Picture	Note	
BJ-WT01	1.2mLong	LLDPE	US\$90		Minimum Order Quantity:10pcs	
BJ-WT02	5mx2.6mx1.9mH	0.9mm PVC Tarpaulin	US\$868		Air pump,repair kits Included	
BJ-WT03	5mDiameter	0.9mm PVC Tarpaulin	US\$920		Air pump,repair kits Included	
BJ-WT04	5mDiameter	0.9mm PVC Tarpaulin	US\$1,090		Air pump,repair kits Included	
BJ-WT05	1.5mLong	LLDPE	US\$160		Minimum Order Quantity:10pcs	
BJ-WT06	3mDiamter	0.9mm PVC Tarpaulin	US\$530	Cherry List of Confession	Air pump,repair kits Included	
BJ-WT07	5.2mx1.2mx1mH	0.9mm PVC Tarpaulin	US\$360		Air pump,repair kits Included	
BJ-WT08	2.5mx2.4mx1.2mH	0.9mm PVC Tarpaulin	US\$490		Air pump,repair kits Included	

BJ-WT09	5.5mx2mx2m	0.9mm PVC Tarpaulin	US\$650		Air pump,repair kits Included
BJ-WT10	1.9mx0.8mx0.8m	0.9mm PVC Tarpaulin	US\$240		Air pump,repair kits Included
BJ-WT11	2.9mx1.7mx1m	0.9mm PVC Tarpaulin	US\$353		Air pump,repair kits Included
BJ-WT12	3mDiamter	0.9mm PVC Tarpaulin	US\$680	www.big-joys.com	Air pump,repair kits Included
BJ-WT13	1.6mL	0.9mm PVC Tarpaulin	US\$135/pair	irun	Air pump,repair kits Included
BJ-WT14	11mx4.5mx1.6mH	0.9mm PVC Tarpaulin	US\$650		Air pump,repair kits Included
BJ-WT15	1.6mx1.1mx0.6mH	0.9mm PVC Tarpaulin& LLDPE	US\$350		Minimum Order Quantity: 5 pcs
BJ-WT16	12mx3.5m	0.55mm PVC Tarpaulin	US\$1,180		Air pump,repair kits Included
BJ-WT17	5mDiameter	0.9mm PVC Tarpaulin	US\$1,090		Air pump,repair kits Included
BJ-WT18	12mx1.6mx3.5mH	0.55mm PVC Tarpaulin	US\$890		Air pump,repair kits Included

BJ-WT19	15mx2mx2.5mH	0.55mm PVC Tarpaulin	US\$1,070	CVICY COM	Air pump,repair kits Included
BJ-WT20	7.2mx4.7mx1.7mH	0.9mm PVC Tarpaulin	US\$420	1	Air pump,repair kits Included
BJ-WT21	5.5mx2mx2m	0.9mm PVC Tarpaulin	US\$833		Air pump,repair kits Included
BJ-WT22	5.4mx3.1mx1.0mH	0.9mm PVC Tarpaulin	US\$350	*	Air pump,repair kits Included
BJ-WT23	4.5mHigh	0.9mm PVC Tarpaulin	US\$1,250		Air pump,repair kits Included
BJ-WT24	4mLong	0.9mm PVC Tarpaulin	US\$435		Air pump,repair kits Included
BJ-WT25	6x2.5mx1.8mH	0.9mm PVC Tarpaulin	US\$1,250	e	Air pump,repair kits Included
BJ-WT26	5mx4.3mx2.5mH	0.9mm PVC Tarpaulin	US\$1,300		Air pump,repair kits Included
BJ-WT27	3.7mLong	0.9mm PVC Tarpaulin	US\$300		Air pump,repair kits Included

BJ-WT28	6x3x2.5mH	0.9mm PVC Tarpaulin	US\$1,335		Air pump,repair kits Included
BJ-WT29	6x2.5mx1.8mH	0.9mm PVC Tarpaulin	US\$1,250		Air pump,repair kits Included
BJ-WT30	7mLong	0.9mm PVC Tarpaulin	US\$335		Air pump,repair kits Included
BJ-WT31	5.3mx4.8m	0.9mm PVC Tarpaulin	US\$950		Air pump,repair kits Included
BJ-WT32	5mx2.6mx1.9mH	0.9mm PVC Tarpaulin	US\$868		Air pump,repair kits Included
BJ-WT33	3.7mx2.5mx1.9mH	0.9mm PVC Tarpaulin	US\$420	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Air pump,repair kits Included
BJ-WT34	2.2mDiameter (7'D)	0.9mm PVC Tarpaulin	US\$530		Air pump,repair kits Included
BJ-WT35	2mx1.5m	0.9mm PVC Tarpaulin	US\$230		Air pump,repair kits Included
BJ-WT36	2.4mx2.1m	1.0mm PVC Sheet	US\$470		Air pump,repair kits Included
BJ-WT37	2.5mx2m	0.9mm PVC Tarpaulin	US\$580		Air pump,repair kits Included

BJ-WT38	1.6mx1.1mx0.48mH	0.9mm PVC Tarpaulin& LLDPE	US\$300	W. blyejoyste	Minimum Order Quantity:5pcs
BJ-WT39	6mx2.1m	0.9mm PVC Tarpaulin	US\$350		Air pump,repair kits Included
BJ-WT40	8mx0.8m	0.9mm PVC Tarpaulin	US\$400		Air pump,repair kits Included
BJ-WT41	4.2mx4.2mx1.8mH	0.9mm PVC Tarpaulin	US\$1,000		Air pump,repair kits Included
BJ-WT42	2.2mDiameter	0.9mm PVC Tarpaulin	US\$820	Avv. b 195 oys som	Air pump,repair kits Included
BJ-WT43	3.6mx5.5mx3.6mH 12'x18'x12'H	0.9mm PVC Tarpaulin	US\$1,100		Air pump,repair kits Included
BJ-WT44	5.5mx3mx3mH 18'x10'x10'H	0.9mm PVC Tarpaulin	US\$1,335		Air pump,repair kits Included
BJ-WT45	2.8mx2.8mx2mH	0.9mm PVC Tarpaulin	US\$725		Air pump,repair kits Included
BJ-WT48	25m diameter,the pool size is 18m daimeter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,000		Air pump,repair kits Included

BJ-WT50	28m diameter,the pool size is 21m diameter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,300		Air pump,repair kits Included
BJ-WT51	30m diameter,the pool size is 24m daimeter ,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,500	TANISSI OF THE STATE OF THE STA	Air pump,repair kits Included
BJ-WT52	38m diameter,the pool size is 30m daimeter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,800	CONTRACTOR OF THE PARTY OF THE	Air pump,repair kits Included
BJ-WT53	35m diameter,the pool size is 25m diameter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$11,400		Air pump,repair kits Included
BJ-WT54	a whole set of inflatable water park	0.9mmPVC Tarpaulin	US\$8,710		Air pump,repair kits Included
BJ-WT55	17m diameter,the pool size is 10m diameter,the pool high is0.8m	0.9mm&0.55MM PVC Tarpaulin	US\$5,500		Air pump,repair kits Included
BJ-WT56	28m diameter,the pool size is 21m diameter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,300	at the light of th	Air pump,repair kits Included
BJ-WT57	30m diameter,the pool size is 24m daimeter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$14,000		Air pump,repair kits Included
BJ-WT58	25m diameter,the pool size is 20m diameter,the pool high is 1 m	0.9mm&0.55MM PVC Tarpaulin	US\$12,000		Air pump,repair kits Included

^{*}The above price including CE/UL Blowers,Repair kit bag

^{*}Price is based on EXW Zhengzhou, China

^{*}Dimension,Color&Price are changed without notice,Price is subject to our confirmation

^{*}Packing in Carpet(Inner)+PVC Bag(Outer) or Cartons

^{*}Payment to be made by Bank Wire Transfer(T/T), Western Union or Paypal